

09/689,817

	Type	L #	Hits	Search Text	DBs	Time Stamp	Cor m e n t s	Er r o r D e f i n i t i o n	Er r o r s
1	IS&R	L1	749	(429/212,213).CCLS.	USPA T; US-P GPUB	2003/03/3 1 18:57			0
2	BRS	L2	100	1 and (plasticizer plasticizing plasticating)	USPA T; US-P GPUB	2003/03/3 1 18:58			0
3	BRS	L3	82	2 and ((electrode anode cathode) with (thick thickness))	USPA T; US-P GPUB	2003/03/3 1 19:50			0
4	BRS	L4	40	3 and ((electrode anode cathode) with (Pore porosity porous micropore microporous microporosity))	USPA T; US-P GPUB	2003/03/3 1 19:04			0
5	BRS	L5	42	3 not 4	USPA T; US-P GPUB	2003/03/3 1 19:50			0

09/689817

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L2	478	(429/213) .CCLS.	USPA T; US-P GPUB	2003/10/0 8 16:59			0
2	IS&R	L3	1	("6551747") .PN.	USPA T	2003/10/0 8 16:19			0
3	BRS	L4	11	("3520729"   "4324828"   "5180642"   "5571636"   "5582935"   "5667916"   "5670276"   "5716422"   "5744258"   "6045942"   "6258473") .PN.	USPA T	2003/10/0 8 16:17			0
4	IS&R	L5	1149	(429/212,213,211) .CCL S.	USPA T; US-P GPUB	2003/10/0 8 16:20			0
5	IS&R	L6	1061	(264/176.1) .CCLS.	USPA T; US-P GPUB	2003/10/0 8 16:20			0
6	BRS	L7	2210	5 6	USPA T; US-P GPUB	2003/10/0 8 16:20			0
7	BRS	L8	118	7 and @PD>20030315	USPA T; US-P GPUB	2003/10/0 8 17:15			0
8	BRS	L9	63	2 and (thickness with collector)	USPA T; US-P GPUB	2003/10/0 8 16:21			0
9	BRS	L10	40	2 and (thick with collector)	USPA T; US-P GPUB	2003/10/0 8 16:21			0
10	BRS	L11	77	9 10	USPA T; US-P GPUB	2003/10/0 8 16:21			0
11	BRS	L12	77	11 and (thickness thick)	USPA T; US-P GPUB	2003/10/0 8 16:22			0
12	BRS	L13	88	8 not 2	USPA T; US-P GPUB	2003/10/0 8 17:15			0
13	BRS	L14	88	13 not 12	USPA T; US-P GPUB	2003/10/0 8 17:15			0
14	BRS	L15	61	14 and (thick thickness)	USPA T; US-P GPUB	2003/10/0 8 17:18			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
15	BRS	L17	2488	H01M004/60	EPO; JPO; DERW ENT	2003/10/0 8 17:20			0
16	BRS	L18	117	17 and (thick thickness)	EPO; JPO; DERW ENT	2003/10/0 8 17:20			0
17	BRS	L19	89	17 and volume	EPO; JPO; DERW ENT	2003/10/0 8 17:20			0
18	BRS	L21	86	19 and (battery cell electrode anode cathode)	EPO; JPO; DERW ENT	2003/10/0 8 17:21			0
19	BRS	L20	114	18 and (battery cell electrode anode cathode)	EPO; JPO; DERW ENT	2003/10/0 8 17:35			0
20	BRS	L22	80	21 not 20	EPO; JPO; DERW ENT	2003/10/0 8 17:35			0
21	BRS	L23	241	(FUJIWARA near3 MASAKI).in.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:41			0
22	BRS	L24	392	(NAKAGAWA near3 YUJI ).in.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:42			0
23	BRS	L25	38	(KUROSAKI near3 MASATO ).in.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:43			0
24	BRS	L26	26	(KANEKO near3 SHINAKO ).in.	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:44			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
25	BRS	L27	48	(HARADA near3 GAKU ) .in.	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:45			0
26	BRS	L28	277	(NISHIYAMA near3 TOSHIHIKO ) .in.	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:45			0
27	BRS	L29	854	23 24 25 26 27 28	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46			0
28	BRS	L30	205	29 and (Battery cell electrode anode cathode)	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46			0
29	BRS	L31	77	30 and H01M\$8	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46			0
30	BRS	L32	26	31 and (thick thickness volume)	USPAT; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:47			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
31	BRS	L33	25	32 not 22	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:47			0
32	BRS	L34	25	33 not 15	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2003/10/0 8 17:47			0